



WATER QUALITY M E M O R A N D U M

Utah Coal Regulatory Program

September 12, 2007

TO: Internal File

THRU: Pamela Grubaugh-Littig, Permit Supervisor 

FROM: David Darby, Environmental Scientist III/Hydrologist 

RE: 2006 2nd Quarter Water Monitoring, Savage Services Corporation, Savage Coal Terminal, C/007/0022, Task ID #2564

The Savage Coal Terminal is an operating coal loadout where coal is crushed, screened, blended, and then loaded onto rail transport.

Pertinent water monitoring requirement information is in the MRP in Sections 7.16, and 7.2.5, and figure 7-15.

1. Was data submitted for all of the MRP required sites? YES X NO

Springs –

The Permittee is not required to monitor any springs at the Savage Coal Terminal. There are no springs to monitor.

Streams –

The Permittee is required to sample CV-14-W, for the parameters outlined in Figure 7-15 in the second and fourth quarter of each year.

Wells–

The Permittee is required to sample CV-1-W for the parameters outlined in Figure 7-15 in the second and fourth quarter of each year.

UPDES

There is one active UPDES outfall at the Savage Coal Terminal, CV-15-W, or UTG040005-001. The Permittee is required to monitor this UPDES site monthly.

2. Were all required parameters reported for each site? YES ☐ NO ☒

Contact was made with Mr. Dan Guy to discuss the missing data for June September 12, 2007. He stated the UPDES site recorded no flow during the period.

3. Were any irregularities found in the data? YES ☒ NO

As identified in Section 2.

4. On what date does the MRP require a five-year re-sampling of baseline water data.

Does not specify. Will request during Midterm review.

5. Based on your review, what further actions, if any, do you recommend?

The UPDES information has to be updated in the database.

an
O:\007022.SAV\WATER QUALITY\DWDWQ_06-2_2564.DOC